



NORTHEAST SERVICE SHOP

SERVICE AND SUPPORT FOR RECIPROCATING ENGINE & COMPRESSION EQUIPMENT

Cooper's Huntington, West Virginia service shop, parts distribution warehouse and manufacturing center offers a diverse array of services, including in-house engine and compressor repairs and overhauls, parts manufacturing, and parts warehousing.

Established in 1997, the Huntington service center specializes in parts supply and repair of large-bore integrals such as Cooper-Bessemer, Clark, Ingersoll Rand, and Worthington. Huntington also has a full weld shop and metallizing department.

Core Capabilities

The St. Rose service shop is a Cooper regional shop/warehouse for genuine O.E.M. parts and service, covering the following reciprocating compression and engine products:

- | | | |
|--------------------|------------------|----------------|
| › AJAX® | › Enterprise® | › Texcentric® |
| › CAT | › Gemini® | › TSI® |
| › Clark | › Ingersoll Rand | › Waukesha VHP |
| › Cooper-Bessemer® | › Superior® | › Worthington |

This location specializes in the following types of service and repair:

- › Sales/Service/Engineering
- › Compressor rod manufacturing
- › Connecting rod manufacturing and repair
- › Compressor pistons
- › Cylinder manufacturing and refurbishment
- › Tungsten coating of piston rods
- › Manifold fabrications (exhaust, water, and air)
- › General fabrication
- › Field machining capabilities
- › Welding and metallizing capabilities
- › Unit exchange program
- › Hydrostatic testing
- › 24-hour service
- › Project management



This location has the following specialty machining tools:

- › Winrock analyzers
- › Hytorc equipment
- › Optical/laser alignment
- › Wireline
- › Vibration analysis equipment
- › Digital engine balancing equipment
- › Customized field service trailers
- › Certified engine lifting equipment

Proven Results

Our Huntington service center successfully manufactured a new custom-designed air intake manifold for a Clark TCVC-20 (12,000 hp) for a customer in Mississippi. Cooper engineers designed the two-piece manifold to replace a cracked one-piece bank manifold. The new manifold is a drop-in replacement of the original, and the two 20' sections are much easier to handle and install than the one piece.



YEARS ESTABLISHED	1997
FACILITY FOOTPRINT	5 ac
TOTAL SIZE	20,000 sq. ft.
SHOP	15,000 sq. ft.
OFFICE	5,000 sq. ft.
SERVICE TRUCKS/TRAILERS	✓
CRANES	
3 TON	1
7.5 TON	1



Northeast Regional Director
 Greg Penzato
 Office (504) 461-3532
 Mobile (504) 481-8440
Greg.Penzato@CooperServices.com

Northeast Service Supervisor
 Dustin Jones (812) 653-1627

Senior Sales Manager
 Ed Bittner (585) 282-7591

Account Managers
 Allen Larabee (281) 840-3189
 Don Taylor (724) 777-1602

Huntington Machine Shop Manager
 Mark Ash (304) 962-6758

Huntington Shop Supervisor
 Terry Crawford (304) 544-9412

NortheastSales@CooperServices.com